Health Check Schematic

Received PO/order

↓

ON Site Visit

↓

Optional CFD

↓

Report Preparation
A soft copy is sent to the customer to facilitate changes or additions to the process

↓

Final Report/Presentation

Pre Inspection Meeting and Documentation Request

To agree specification and scope of consultancy. Request floor plans, equipment listings, design specifications etc.

On Site, Visual Inspection

Audit covering:-

Thermal environment
Air pressures
Physical security
Cooling
Lighting
Health and Safety
Cabling
Power
Any Process
Monitoring
Management Structure

Creation of a Virtual, 3D Model of your Facility

1) Walk-through a full 3-dimensional inventory of all recognised equipment housed within your facility;
2) Visualise the temperature distribution and airflow at both room and cabinet level;
3) Track historic changes in equipment layout;
4) Preview planned, future equipment deployment;
5) Evaluate the thermal/environmental impact of these options prior to deployment.